



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

July 19, 2007

Supervisor 10024

**Mine Name:** Northshore Natural Process  
**Operator Name:** Northshore Limited Partnership

**Permit number:** M/003/037  
**Inspection Date:** July 18, 2007  
**Time:** 4:30 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** Corey Anderson, Ron Purser, Oscar Guzman  
**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a routine inspection while in the area.

#### Inspection Summary:

This site was active. Mr. Anderson informed me that Lee Medford is no longer employed by Northshore and that he is now the contact for this site. He also indicated that the corporate structure had changed. I requested that he send us replacement pages for the NOI to update these changes. Permit fees have not yet been paid. Mr. Anderson did not recall seeing the billing statement but will double check so that he can get it paid.

The disturbed area is fenced to keep the general public out of the evaporation ponds. The only facilities outside the fenced area are the care-taker's trailer and the trench to collect water from the Great Salt Lake. Currently, the lake level is so low that the trench is nearly 4 miles long. There were no erosion or trash problems noted during this inspection.

Photos were taken to document site conditions. However, the operator asked if we could keep photos confidential, explaining that photos may document proprietary information regarding their operations that they wanted to keep from their competition. Mr. Anderson will follow up this request in writing.

#### Conclusions and Recommendations:

The site is in compliance at this time. Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M003-BoxElder\M0030037-NorthshoreLimited\inspections\Insp-07182007.doc